

CU362 Dedicated Controls Simulator and Windows 10

If you get then below error message "Failed to run tool", you need to **copy** the odbc32.dll file from "c:\Windows\System32" folder, and replace the odbc32.dll file in the "c:\Program Files (x86)\Grundfos\CU 362 DC Simulator..." folder.

